Massey Ferguson 6713 2023

Make	Massey Ferguson
Model	6713
Construction year	2023
Serial Number	6713689096
Inspection date	13 Jan 2026
Address of the inspection	Aparecida de Goiânia
























MARISPAN
MX05


MARISPAN
MX05
GROVALE








General

	Value	Note	
Serial No			1, 2
Chassis no			3, 4




1



2



3





4

Open Hood


	Value	Note	
Engine			5
Pump & Nozzle			6
Electrical			7, 8, 9, 10
Radiator			11, 12
Battery photo			13
Running Engine			
Hydraulic oil leaks	No		14







11




6



9




12







13



14

Equipment interior

	Value	Note	
Hours			15
Seat			16
A/C Controle		NAO	17
Roof			18
Gearbox			19, 20
gearbox-option	Multiplier		21
Steering-Wheel			22
Pedals			23
Hydraulic Controls photo			24, 25, 26
command-type	Simple Command		27
Monitor		NAO	28
Auto Guidance ready	No		
Transmission	Semi-automatic		29



15



16



17






19








22







25




27



28


29

Tyres

	Value	Note	
Right Back Tyre			30
Right Back Tyre Condition	Regular		
Tyre image			31
Left Back Tyre Condition	Regular		
Left Front Tyre			32
Left Front Tyre Condition	Regular		
Right Front Tyre			33
Right Front Tyre Condition	Regular		
Tyre Condition	Regular		
Double Wheel		NAO	34, 35
Tyre brand	Goodyear		
Tyre Tread			36
Tyre Tread Left Back			37
Tyre Tread Right Front			38
Tyre Tread Right Back			39




30



31




32






34







37



38



39

Extra options

	Value	Note	
Are there any additionals?			40
Breakdowns (more than 1 if necessary)			41, 42, 43, 44, 45, 46, 47, 48, 49





41







44





46



47



48



49

Remarks

	Value	Note	
Outside	★★★☆	EQUIPAMENTO COM RISCOS NA PINTURA PEQUENO AMASSADO NO TETO PARALAMAS ARRANADOS FALTA BRAÇO DO 3°PONTO CARANAGENS DA LANTERNA DIREITA SOLTA E COM AVARIAS .	50
Engine status	★★★★		
Interior	★★★☆		



50

Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.