

Valtra VT BH 194 2022

Make **Valtra**

Model **VT BH 194**

Construction year **2022**

Serial Number **W194656980**

Inspection date **03 Nov 2025**

Address of the inspection **Lavras**







General

	Value	Note	
Serial No			1
Chassis no			2





1



2

Open Hood

	Value	Note	
Engine			3, 4, 5
Pump & Nozzle			6
Radiator			7
Battery photo			8
Running Engine			
Hydraulic oil leaks	No		



Equipment interior

	Value	Note	
Hours			9
Seat			10
A/C Controle			11
Cabin window			12, 13, 14, 15, 16, 17
Roof			18, 19
Gearbox			20
gearbox-option	Reversor		
Steering-Wheel			21
Pedals			22
Hydraulic Controls photo			23
command-type	Double Command		
Auto Guidance ready	No		
Transmission	Semi-automatic		













9



10



11



21

22

23

Tyres

	Value	Note	
Right Back Tyre			24, 25
Right Back Tyre Condition	Bad		
Tyre image			26
Left Back Tyre Condition	Bad		
Left Front Tyre			27
Left Front Tyre Condition	Critical		
Right Front Tyre			28
Right Front Tyre Condition	Critical		
Tyre Condition	Bad		
Tyre brand	Goodyear		
Tyre Tread			29, 30
Tyre Tread Left Back			31
Tyre Tread Right Front			32
Tyre Tread Right Back			33



24




25



26




28



31



32



33

Remarks

	Value	Note	
Outside	   		
Engine status	   		
Interior	   		

Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.