

JCB DO BRASIL LTDA 422ZX 2022

Make	JCB DO BRASIL LTDA
Model	422ZX
Construction year	2022
Serial Number	3079862
Inspection date	10 Dec 2025
Address of the inspection	Ananindeua

General

	Value	Note	
Engine power	kw		1
Fuel Type	Diesel		
Hourmeter reading	h		
Serial no.	307986		
Original body colour	Yes		
Colour	amarelo eu		
Object status	Used		
Registration number	3079862		



1

Papers

	Value	Note	
CE marked	No		

Vehicle history

	Value	Note	
Part manual	No		
User manual	No		
Maintenance book	No		
Serviced	No		
There is a stamped servicebook available	No		
Bills of maintenance can be provided	No		
General state of function			
Dealer Maintained	No		
Interior			
Electrical system			
Lamps			
Drivetrain			
Paint			
Hydraulics			
Steering mechanism			
Chassis			
Exhaust System			
Damaged	sim		
Number of previous owners	somente um		
Final inspection	máquina danificada		

Extra options

	Value	Note	
Closed cabin	Yes		
A/C	Yes		
Driver seat air-cushioned	Yes		
Alarm	No		
Immobiliser	No		
Radio	No		
Tinted glass	Yes		
Pressurized Unit	No		
Extra connections gas oil pump	No		
Flashing light	No		
Additional halogen workinglamps	No		
Central lubrication system	Yes		
Emergency shut off switch	Yes		
Carkit	No		
Extra storage under or on top of the frame	No		
CB radio	No		
Heated	No		
Specialty	construção		
Battery divider	Yes		
Blade	No		
Body exhaust heating	No		
Diesel heater	No		
Load damping	Yes		
Guide rails	No		

Line rupture valve boom	Yes
Heater	No
Mud guards	Yes
Outriggers	No
Payload system	Yes
Plough	No
Stick	No

Tyres

	Value	Note	
Front tyre size	17.5.25		
Rear tyre size	17.5.15		
Tyre types	Air		
Front tyres	100% %		
Rear tyres	100% %		

Configuration loading frame

	Value	Note	
Front loader	Yes		
General condition linkage	100%		
System	Other		

Attachments

	Value	Note	
Pins and bushings	★ ★ ★ ★		
Hose and pipe kit	Yes		
Demolition and sorting function	Yes		
Attachments and Parts	250.000,00		
Quick hitch	No		
Quick hitch brand	não		
Hammer hydr. Function	No		
Hammer/shear hydr. Circuit	No		

Hydraulics

	Value	Note	
Hose burst protection lifting cylinder	No		
Hose burst protection pipe cylinder	No		
Other hose burst protection	No		
Bucketcylinder	Yes		
Bend cylinder	Yes		
Lifting cylinder	Yes		
3rd hydr. circuit	No		
Extra hydraulics	não		
Inclination hydraulics	Yes		

Accessories

	Value	Note	
Excavator Bucket	★ ★ ★ ★		
Rubbish farmfork	★ ★ ★ ★		
Stone clamp	★ ★ ★ ★		
(Other) fittings	não		
Content excavator bucket	no momento sem motor é impossibilitado de uso		
Cable excavator bucket	sem cabo		

Engine

	Value	Note	
Number of cylinders	5		2, 3
Cylinder capacity	8 cc		4, 5
Engine manufacturer	jcb		6, 7
Motor type	diesel max		8, 9



Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.