

Valtra BS 3020 2016

Make **Valtra**

Model **BS 3020**

Construction year **2016**

Serial Number **3020422142**

Inspection date **04 Dec 2025**

Address of the inspection **Itapeva**









General

	Value	Note	
CE marking		Está sem carga bateria,	
Certificates		Não co	
Usage meter		Sem carga bateria	
Working width	28 mm		
User manual	No		
Registration Documents	No		
License plate		Não consta	

Control station

	Value	Note	
Seat / Armrests / Seat belt / Suspension	   		
Passenger seat	   		
Armrests controls	Yes		
Dashboard	   		
Default codes from the computer system		Bateria sem carga	
On-board computer with screen	No		
Aircon / Heater	No function	Não está funcionando	
Glass / Mirrors	   		
Wipers / Washer		Não funciona	
Cab Video			

Electrical

	Value	Note	
Lights work	No		
Warning lights work / Gauges work	No		

Engine

	Value	Note	
Exhaust system	   		
Cooling package	   		
Leaks - Fuel/Oil/Coolant	Yes		
Fluid Level (Oil/Coolant)	Good		

Chassis

	Value	Note	
Tank	   		
Induction Bowl	   		
Pumps			1, 2
Valves	   		3
Axles	   		4, 5



Hydraulics

	Value	Note	
Hydraulic oil level	Good		
Hydraulic oil leaks	None observed		
Hydraulic cylinder condition	★ ★ ★ ★		
Hydraulic Hoses / Lines	★ ★ ★ ★		
Functions Test Video		Não tem como ligar a máquina	

Configuration boom

	Value	Note	
Nozzles			6
Boom condition			7
Boom Mounting Frame			8
Boom Section Valves	★ ★ ★ ★		
Hoses / Pipes / Lines	★ ★ ★ ★		



6



7



8

Accessories

	Value	Note	
Camera	No		
Flashing light	No		
GPS Antenna		Não consta	
Any Additional Display Screens	No		
(Other) fittings		Não consta	

Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.